



MRCSS Bug Mod 1 January 26 2013
6% thick foil .13 % Camber
As per Builder's options/leading/trailing edge etc.









