


cut after mounting in fuselage



center motor

cut after mounting in fuselage

F1-F3 and N1+N2 in 6mm depron