

COCKPIT NACELLE IS ONLY EPOXIED TO CENTRE SECTION AFTER BOOMS AND STABILISER FITTING AND ALIGNMENT ON WING HAVE BEEN COMPLETED



ALIGN THIS SURFACE OF NACELLE PARALLEL TO AND LEVEL WITH TOP LINE OF BOOMS

